Larry Mcblocer 04/05/2004 eina Higgins Atlantic 497-6729 213-486-35/ herge Mass -Rick - Tank Ferro Magnetic finder \$295 for Detects Iron by measuring the thickness of the iron 6 weeks - 2 months Arco Products Co, 1055 W. 7+1St. P.O. Box 2570 LIA. CA 9005 Fax - 213-486-1282

12/4/92

2840

3930

STARTED TEST, PER P. CAFFREY (APT TECH, INC)

AREA LOOKS AS IF REMOVAL HAS BEEN DONE

CONCRETE PADS HAVE BEEN TAKEN OUT AND HAVE

BEEN RECOVERED, THERE SEEM TO HAVE BEEN A

TRENCH DUG OUT BETWEEN AREA WHERE

PUMPS ONCE WERE TO CONNER OF PROPERTY.

THIS WOULD INDICATE VENT UNES FROM TANK AREA

FERRO MAGNETIC DETECTOR

HAND HELD WAND

PROCEOUNES SWEEPING MOTION WITH

DETECTOR OVER LOT AREA, IF ANY THING FOUND

TONE FROM DETECTOR WOULD RING ALEAT.

FOUND OIL TANK REAR OF BLDG. L FUEL OIL FOR
APPROXIDATELY 500 GAL, HEAT OF CAK WASH

2 DRUMS ARE LOCATED SAME AREA.

THEY ARE THE OIL WATER SEPARATION, REW WATER TO WASH CARS

I CONCRETE HATCH NEAR OIL TANK + VENT SEPTIL

THERE IS A VENT (SAME AREA OF TANK)

SYSTEM

APPROXIMATELY 8' FROM HATCH. THE REMOVED_

PROBABLY CLEAN OUT VENT __ 4 HATCHES TO SHOW NOTE * A GREEN PASTE THAT TURNS BLUE ONLYWATER WHEN IN CONTACT WITH WATER.